

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Eastern Honcut Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Van Tress	Left	1.46	10/05/2016 10/05/2016	Sterling York

LM Start		Rating **	M	Issue No.	6
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_NA0006_01_s _ 2013_6				
Comment Code					
Inspector Comment					
This levee is maintained by the private land owner, Jimmy Vantress, and should be contacted before entering the property. Phone number is (530) 682-5874. The code to the gate is 0911. The LMA has stated in the past that they do have access to flood fight supplies.					

No Photos

LM Start		Rating **	M	Issue No.	9
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_NA0006_01_s _ 2012_9				
Comment Code					
Inspector Comment					
The LMA does not regularly attend Flood Fight classes put on by DWR.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Eastern Honcut Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Van Tress	Left	1.46	10/05/2016 10/05/2016	Sterling York

LM Start		Rating **	M	Issue No.	10
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals			°	°
DWR ID	DWR_NA0006_01_s_2012_10				
Comment Code					
Inspector Comment					
No manual was available during the inspection.					

No Photos

LM Start	0.02	Rating **	U	Issue No.	19
LM End	0.02	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.298500°	39.298500°
				-121.569508°	-121.569508°
DWR ID	DWR_NA0006_01_f_2016_19				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Remove Blackberry bushes covering waterside levee slope.					

Photo 1 of 1 : FA_2016_NA0006_252_19_20161005_00024.jpg



View of Blackberry bushes covering waterside levee slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Eastern Honcut Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Van Tress	Left	1.46	10/05/2016 10/05/2016	Sterling York

LM Start	0.02	Rating **	M	Issue No.	12
LM End	1.45	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.298508 °	39.295263 °
				-121.569507 °	-121.546580 °
DWR ID	DWR_NA0006_01_f _ 2016_12				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Annual vegetation needs to be maintained. Fall 2016.					

Photo 1 of 2 : FA_2016_NA0006_252_12_20161005_00029.jpg



View looking upstream landside of annual vegetation that needs to be maintained. Fall 2016.

LM Start	0.02	Rating **	M	Issue No.	12 (cont)
LM End	1.45	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : FA_2016_NA0006_252_12_20161005_00030.jpg



Second view looking upstream landside of annual vegetation that needs to be maintained. Fall 2016.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Eastern Honcut Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Van Tress	Left	1.46	10/05/2016 10/05/2016	Sterling York

LM Start	0.02	Rating **	M	Issue No.	18
LM End	1.45	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.298509 °	39.295263 °
				-121.569507 °	-121.546580 °
DWR ID	DWR_NA0006_01_f_2016_18				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 2 : FA_2016_NA0006_252_18_20161005_00031.jpg



View looking upstream waterside of annual vegetation that needs to be maintained. Fall 2016.

LM Start	0.02	Rating **	M	Issue No.	18 (cont)
LM End	1.45	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : FA_2016_NA0006_252_18_20161005_00032.jpg



Second view looking upstream waterside of annual vegetation that needs to be maintained. Fall 2016.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

Eastern Honcut Creek

View of a tree that needs the limbs trimmed up 5' for visibility and access on the waterside. Fall 2016.

Page 5 of 9

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Eastern Honcut Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Van Tress	Left	1.46	10/05/2016 10/05/2016	Sterling York

LM Start	0.10	Rating **	M	Issue No.	22
LM End	0.10	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.299078 °	39.299078 °
				-121.568633 °	-121.568633 °
DWR ID	DWR_NA0006_01_f _ 2016_22				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					
A tree that needs the limbs trimmed up 5' for visibility and access on the waterside. Fall 2016.					

Photo 1 of 1 : FA_2016_NA0006_252_22_20161005_00026.jpg



View of a tree that needs the limbs trimmed up 5' for visibility and access on the waterside. Fall 2016.

LM Start	0.21	Rating **	U	Issue No.	24
LM End	0.24	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.298836 °	39.298768 °
				-121.566572 °	-121.565921 °
DWR ID	DWR_NA0006_01_f_2016_24				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Remove Blackberry bushes covering the waterside slope.					

Photo 1 of 1 : FA_2016_NA0006_252_24_20161005_00034.jpg



View of Blackberry bushes that cover the waterside slope. Fall 2016.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Eastern Honcut Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Van Tress	Left	1.46	10/05/2016 10/05/2016	Sterling York

LM Start	0.21	Rating **	U	Issue No.	23
LM End	0.21	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.298816 °	39.298816 °
				-121.566529 °	-121.566529 °
DWR ID	DWR_NA0006_01_f_2016_23				
Comment Code					
T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					
Trees that needs the limbs trimmed up 5' for visibility and access on the landside. Fall 2016.					

Photo 1 of 1 : FA_2016_NA0006_252_23_20161005_00027.jpg



View of trees that needs the limbs trimmed up 5' for visibility and access on the landside. Fall 2016.

LM Start	0.23	Rating **	M	Issue No.	25
LM End	0.23	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.298776°	39.298776°
				-121.566158°	-121.566158°
DWR ID	DWR_NA0006_01_f_2016_25				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					
Tree that needs the limbs trimmed up 5' for visibility and access on the waterside. Fall 2016.					

Photo 1 of 1 : FA_2016_NA0006_252_25_20161005_00028.jpg



View of a tree that needs the limbs trimmed up 5' for visibility and access on the waterside. Fall 2016.

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

Eastern Honcut Creek

View of Blackberry bushes that cover the landside slope. Looking upstream. Fall 2016.

View of Blackberry bushes that cover the waterside slope. Looking upstream. Fall 2016.

Page 8 of 9

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Eastern Honcut Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Van Tress	Left	1.46	10/05/2016 10/05/2016	Sterling York

LM Start	0.85	Rating **	M	Issue No.	1
LM End	0.96	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.294995 °	39.295021 °
				-121.557823 °	-121.555813 °
DWR ID	DWR_NA0006_01_f _ 2016_1				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Remove Blackberry bushes starting to take over waterside slope.					

Photo 1 of 1 : FA_2016_NA0006_252_1_20161005_00037.jpg



View of Blackberry bushes that are starting to cover the waterside slope. Looking upstream. Fall 2016.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---